



Chandigarh Pollution Control Committee
Ground Floor, Paryavaran Bhawan, Sector 19-B, Madhya Marg
Chandigarh-160019

Form IV
(See Rule 13)

ANNUAL REPORT

[To be submitted to the prescribed authority on or before 30th June every year for the period from January to December of the preceding year, by the occupier of Health Care Facility(HCF),or Common Bio-medical Waste Treatment Facility (CBMWTF)]

Return No : 406160

Period : 2021

1. Particulars of the Occupier	
(i) Name of the authorized person (Occupier or operator of facility):	Nitasha Gupta
(ii) Name of HCF or CBMWTF:	INDIRA IVF HOSPITAL PVT LTD
(iii) Address for Correspondence:	#362, Near Bell Factory, Sector 16, Panchkula
(iv) Address of Facility:	SCO 156-159, Sector 9-C, Madhya Marg, Chandigarh Sector 9 Po Chandigarh Chandigarh
(v) Tel. No.:	9896978745
(vi) Fax. No.:	-
(vii) E-mail ID:	admin.chandigarh@indiraivf.in
(viii) URL of Website:	
(ix) GPS coordinates of HCF of CBMWTF:	
(x) Ownership of HCF or CBMWTF:	Private
(xi) Status of Authorization under the Bio-medical Waste Management Rules 2016:	Authorization No.: CPCC/BMW/285/2021/219/2975 Valid Upto: 28/10/2023
(xii) Status of Consents under Water Act and Air Act.:	Valid Upto: 31/03/2024
2. Type of Health Care Facility	
HCF/CBMWTF Type:	HCF
(i) No. of Beds(for Bedded Hospital):	12
(ii) Non-Bedded Hospital (Clinic or Blood Bank or Clinical Laboratory or Research Institute or Veterinary Hospital or any other):	00
(iii) Licence Number:	2975
(iv) Licence date of expiry:	28/10/2023
3. Quantity of waste generated or disposed in Kg per annum (on monthly average basis)	Yellow Category: 720 Red Category: 810 White Category: 49 Blue Category: 114 General Solid Waste: 00
4. Details of the Storage, Treatment, Transportation, Processing and Disposal Facility Details	
(i) Details of the on-site storage facility:	Size: 00 Capacity: 00 Provision of on-site storage: 00

(ii) Disposal Facility:	<table border="1"> <tr> <th data-bbox="874 107 1010 248">Type of Treatment Equipment</th> <th data-bbox="1011 107 1147 248">Number of Units</th> <th data-bbox="1149 107 1284 248">Capacity(Kg/day)</th> <th data-bbox="1286 107 1422 248">Quantity Treated or Disposed(Kg/annum)</th> </tr> <tr> <td colspan="4" data-bbox="874 282 1422 315"><i>List is Empty</i></td> </tr> </table>	Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)	<i>List is Empty</i>			
Type of Treatment Equipment	Number of Units	Capacity(Kg/day)	Quantity Treated or Disposed(Kg/annum)						
<i>List is Empty</i>									
(iii) Quantity of recyclable wastes sold to authorized recyclers after treatment in kg per annum:	0								
(iv) No of vehicles used for collection and transportation of BMW:	00								
(v) Details of incineration, ash and ETP sludge generated, disposal during the treatment of wastes in Kg per annum	<table border="1"> <tr> <th data-bbox="874 481 1054 539">Type of waste</th> <th data-bbox="1056 481 1236 539">Quantity Generated</th> <th data-bbox="1238 481 1422 539">Where disposal</th> </tr> <tr> <td colspan="3" data-bbox="874 551 1422 584"><i>List is Empty</i></td> </tr> </table>	Type of waste	Quantity Generated	Where disposal	<i>List is Empty</i>				
Type of waste	Quantity Generated	Where disposal							
<i>List is Empty</i>									
(vi) Name of the Common BMW Treatment Facility Operator through which wastes are disposed of:	M/S ALLIANCE ENVIROCARE CO. PVT. LTD.								
5. Do you have BMW management committee:	yes								
details:	yes								
6. Training Conducted on BMW Details									
(i) Number of training conducted on BMW Management:	12								
(ii) Number of personnel trained:	15								
(iii) Number of personnel trained at the time of induction:	00								
(iv) Number of personnel not undergone any training so far:	00								
(v) Whether standard manual for training is available:	yes								
(vi) Any other information:	NA								
7. Details of the accident occurred									
(i) No. of accident occurred:	00								
(ii) Number of the persons affected:	00								
(iii) Remedial Action taken:	00								
(iv) Any Fatality occurred, details:	00								
8. Are you meeting the standards of air Pollution from the incinerator? (i) How many times in last year could not met the standards?:	00								
Details of Continuous online emission monitoring systems installed:	00								
9. Liquid waste generated and treatment methods in place. (i) How many times you have not met the standards in a year:	00								
10. Is the disinfection method or sterilization meeting the standards? (i) How many times you have not met the standards in a year?:	00								
11. Any other relevant information:	00								

Name and Signature of the Head of the Institution

Date :12/05/2022

Place : *Sector 9 Po Chandigarh*